

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I B R P 1 00-000000-00 411111 5

01 REPORT SOURCE L 050-0155 021578 022272 9

02 During maintenance activity on the Reactor Depressurizing System control
03 circuitry, the fire pump control switches were inadvertently placed in the
04 inhibit position with both fire pumps not running between 0935 and 1315
05 hours; thus the system was not automatically operable as required by T/S
06 3.1.5A. The fire pump function could have been made fully operable by oper-
07 ator action in the control room if conditions had warranted use of the
08 system. Incident not repetitive.

09 S H A A C K T B R K E Z
17 7 8 11 12 13 14 15 16
18 19 20 21 22 23 24 25 26
27 28 29 30 31 32
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

10 The fire pump control switches on the RDS console have been marked with
11 specific instructions for use of the inhibit position since the error that
12 occurred might not otherwise be positively controlled for all postulated
13 troubleshooting activities. The incident will be reviewed with licensed
14 personnel.

15 E 090 NA A Review of Activity by Operations Personnel

16 Z Z NA NA

17 0000 Z NA

18 0000 NA

19 Z NA

20 N NA

POOR ORIGINAL

990055

7909210421

NRC USE ONLY

7909210421