



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 14, 1979

1-099-13

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011


Subject: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Reportable Occurrence Report  
Nos. 50-313/79-015 and  
50-313/79-016  
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2, we have attached the subject reports concerning a monthly surveillance operational test which resulted in Diesel Generator #2 tripping due to low oil pressure (50-313/79-016).

As requested in IE Bulletin 79-02, an analysis of Seismic Category I pipe supports for baseplate flexibility revealed 37 restraints were identified as having a safety factor of less than two (50-313/79-015).

Very truly yours,

  
David C. Trimble  
Manager, Licensing

DCT:REI:vb

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Russellville, AR 72801

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

1038 325

Acc 2  
5/11