TOFFICE DOLL 450 MIDDLETOWN, FINISYLVANIA 17057

TELEPHONE 717-944-4041

August 23, 1975

11. J.P. 0'7:177 Directors of Regulatory Operations Conten 1 621 Park mue King of Prussia, Pa. 19405

POOR ORIGINAL

Operating License BPR-50 Dacket 50-289

Subject: Abnormal Occurrence No. A0 75-28

Gear Kr. O'Reflly:

This telegram is to confirm the conversation between Lee Spassard (Marion I-NRC) and J.J. Colitz (Till Unit 1 Superintendent) at 1400 hours on 23 July 12.5.

The following report is submitted in accordance with paragraph 1.8.d (page 1-6) of the Technical Specifications.

On August 20, 1975 the Turbine Driven Emergency Feed Pump was run for Surveillance Testing. The pump operated successfully on steam supplied from A Steam Generator through MS VI3A. When an attempt was made to test the pump on steam supplied from the B Steam Generator, the associated valve, MS VI33, opened in response to pressing the open pushbutton but closed when the open pushbutton was released.

Investigation revealed a failed pressure switch. The failed pressure switch would have prevented the valve opening on an automatic start signal.

The pressure switch was replaced and the Turbine Driven Feed Purp top successfully tested on steam supplied from the B Steam Generator within the 4. : r allowable time period.

Unit 1 Superintendent

JUC/C.

1476 177