



METROPOLITAN EDISON COMPANY SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

POST OFFICE BOX 480 MIDDLETOWN, PENNSYLVANIA 17057

TELEPHONE 717-844-4041

July 11, 1975

Mr. J. P. O'Reilly, Director  
Directorate of Regulatory  
Region I  
631 Park Avenue  
King of Prussia, Pa., 19406

POOR ORIGINAL

Operating License DPR-50  
Docket 50-289

Subject: Abnormal Occurrence No. A0-75-22

Dear Mr. O'Reilly:

This telegram is to confirm the telecon with Paul Kellogg (Region I-DRO) and J. P. O'Hanlon (TMI Unit 1 Plant Operations Review Committee Chairman) at 1015, July 11, 1975.

The following report is submitted in accordance with paragraph 6.7.2.a.2 (page 6-11) of the Technical Specifications.

On July 11, 1975, during a routine inspection of the Auxiliary Building, two pin hole leaks were found in socket weld joints of the "A" Make-Up Pump suction line vent. This is considered an abnormal degradation of a boundary designed to contain radioactive liquid.

The leaks have been repaired and a hydro will be performed on the vent line.

The leakage appears to be a result of vibration in the make-up pump suction line being transmitted to the rigidly supported vent line. The support scheme of the vent line has been changed to allow for greater flexibility of the line.

Very truly yours,

J. P. O'Hanlon  
Unit 1 PORC Chairman  
TMI Nuclear Station

JPO:ca

7910240

1476 248  
935