

# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 

01	P	A	T	M	=	1
----	---	---	---	---	---	---

 LICENSE NUMBER: 

00	-	00	00	00	00	-	00
----	---	----	----	----	----	---	----

 LICENSE TYPE: 

4	/	/	/	/
---	---	---	---	---

 EVENT TYPE: 

03
----

CATEGORY: 

01	CON'T
----	-------

 REPORT TYPE: 

4
---

 REPORT SOURCE: 

4
---

 DOCKET NUMBER: 

050	-	0289
-----	---	------

 EVENT DATE: 

03	09	77
----	----	----

 REPORT DATE: 

04	08	77
----	----	----

### EVENT DESCRIPTION

02 | During normal operation, while performing the R.B. Spray System Channel | 80  
03 | Test, The R.B. Spray Pump Station Isolation Valve failed to close with | 80  
04 | a remote control signal. The valve was manually closed, failed to open | 80  
05 | with a remote signal, and was manually opened. The valve motor was | 80  
06 | replaced and the spring pack was cleaned. | 80

SYSTEM CODE: 

07	SA
----	----

 CAUSE CODE: 

5
---

 COMPONENT CODE: 

V	A	L	V	O	P
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

A
---

 COMPONENT MANUFACTURER: 

R	I	G	S
---	---	---	---

 VIOLATION: 

N
---

### CAUSE DESCRIPTION

08 | Grease in the spring pack prevented the torque switch from stopping | 80  
09 | the motor when the valve seated causing the motor to overheat and | 80  
10 | fail | 80

FACILITY STATUS: 

11	E
----	---

 % POWER: 

100
-----

 OTHER STATUS: 

NA
----

 METHOD OF DISCOVERY: 

A
---

 DISCOVERY DESCRIPTION: 

NA
----

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

NA
----

 LOCATION OF RELEASE: 

NA
----

### PERSONNEL EXPOSURES

13 | NUMBER: 

000
-----

 TYPE: 

Z
---

 DESCRIPTION: 

NA
----

 | 80

### PERSONNEL INJURIES

14 | NUMBER: 

000
-----

 DESCRIPTION: 

NA
----

 | 80

### OFFSITE CONSEQUENCES

15 | 

NA
----

 | 80

### LOSS OR DAMAGE TO FACILITY

16 | TYPE: 

Z
---

 DESCRIPTION: 

NA
----

 | 80

### PUBLICITY

17 | Included in weekly news release | 80  
1476 356

### ADDITIONAL FACTORS

18 | Valve motor was replaced and excess grease was removed from | 80  
19 | the spring pack | 80  
7010250566 S

NAME: W. E. Fatts PHONE: 929-3600 (ext. 114)