HEGGLATCHY INFORMATION DISTHIBUTION SYSTEM (PIDS)
DISTHIBUTION FOR INCOMING MATERIAL 50-289

NECI HELD R .

METRUPUL EDISCH

DCCDATE: 02/10/78 DATE RCVD: 02/14/78

DOCTYPE: LEITER

NCTARTZED: NU

LTR 1 ENCL 1

RESPONSE TO NHO LIR DID 12/2/17 FURNISHING INFO CUNCERNING MODIFIED PROGRAM FUR VIBRATIUN TESTING AND ULTHASONIC INSPECTION OF CURRENTLY INSTALLED DECAY HEAT PLMP SHAFTS.

PLANT NAMESTHREE MILE ISLAND . UNIT 1

REVIEWER INITIAL! XEF

******* CISTRIBUTION UF THIS MATERIAL IS AS FOLICHS ************

GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF CPERATING LICENSE.

FUR ACTIUN:

BRANCH CHILL BLID ** H/7 ENCL

INTERNAL :

HEG FILE ***/ENCL

I & E ***/2 ENCL

HANAUER ***/ENCL

EISENHUT ***/ENCL

BAER ***/ENCL

GRIMES ***/ENCL

J. MCGCUGH ***/ENCL

NRC POR***/ENCL
UELD**LTR ONLY
CHECK***/ENCL
SHAD***/ENCL
BUTLER***/ENCL
J COLLINS***/ENCL

EXIERNALS

HARRISBURG, PA**W/ENCL TIC**W/ENCL MSIC**M/ENCL ACHS CAT B***/10 ENCL

POOR ORIGINAL

1490 117

DISTRIBUTION: LTR 40 ENCL 39 SIZE: 2P CCNTRCL NBR: 780460255

7910800 700 mi



MÉTROPOLITAN EDISON COMPANY

POST OFFICE BOX 542 READING, PENNSYLVANIA 19603

February 10, 1978 GQL 0198 TELEPHONE 215 - 929-3601

Director of Nuclear Reactor Regulation Attn: R. W. Reid, Chief Operating Reactors Branch No.4 U.S. Nuclear Regulatory Commission Washington, D.C. 20555 U.S. AUGUSTAN

Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Docket No. 50-289
Operating License No. DPR-50
Decay Heat Pumps

Your letter of December 2, 1977, granted approval of a modified program for vibration testing and ultrasonic inspection of the currently installed decay heat pump shafts that we had requested in our letter of October 27, 1977, GQL 1477, subject to your revision/clarification.

This letter is to inform you that DH-PlA was run in excess of one hour at greater than 550 gpm in a manner not quite consistent with that permitted in your letter of December 2, 1977. The DH-PlA chronology of testing events was as follows:

Time Start	Time Stop	Date	Comments
N/A	N/A	12/05/77	Last pump Vibration/Ultrasonic test; of completed satisfactorily.
0309	0420	01/11/78	First ISI Surveillance Test - Vibration data was recorded incorrectly necessitating verification run.
Times not	available	01/11/78	Engineered Safeguards Surveillance Testing. (Approximately 9 minute run)
2137	2230	01/11/78	Second ISI Surveillance Test. Verified that pump was acceptable and that previous vibration data had most likely been recorded on wrong scale. Shift Supervisor secured DH-PlA operation until Vibration/Ultrasonic program completed on 01/13/78.
			140 118

Total cumulative DH-PlA run time @ > 550 gpm - 133 minutes Total cumulative DH-PlA run time @ < 550 gpm - none 1490 118

N/A N/A 01/13/78

Pump Vibration/Ultrasonic testing completed satisfactorily. 780460255

Although DH-PlA was restarted after having accumulated in excess of one hour of operation at greater than 550 gpm, it was done in order to attain the objectives of the run, i.e., verifying acceptable operation of the pump. Since particular pump ISI tests require bearing temperatures, the pumps have to be run longer to obtain the bearing temperatures than for taking just vibration data. In view of this requirement, Met-Ed is requesting that the greater than 550 gpm accumulated run time be increased to three hours in order to prevent a recurrence of the above situation. Furthern re, this increased accumulated run time should facilitate the monthly ISI testing between the quarterly Vibration/Ultrasonic testing.

Sincerely

J. G. Herbein

Vice President - Generation

JGH:RJS:jmr