

November 1, 1979

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station

Docket No. 50-304/DPR-48

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/79-50 for Zion Generating Station. This occurrence was reported, to Region III, Directorate of Regulatory Operations by telephone on 10/18/79 and by telegram on 10/19/79.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.(9) which states that performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed to the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition requires a 14 day written report.

Very truly yours,

N. E. Wandke Superintendent Zion Station

1355 059

RES/klk

Enclosure: Reportable Occurrence Report No. 50-304/79-50

100/1/1

7911190

439