LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1	N E C P R 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE CODE 14 15 CAT 58
0 1 7 8	SOURCE L 6 0 5 0 0 0 2 9 8 7 1 0 2 6 7 9 8 1 1 2 1 7 9 9 9 EVENT DATE 74 75 REPORT DATE 80
0 2	During normal operation, Technical Specification 3.19A was not met. The doors to
0 3	HPCI & RHR "B" & "D" pump rooms were left open without establishing a fire watch.
0 4	This occurrence presented no adverse consequences from the standpoint of public
0 5	health and safety.
0 6	
0 7	
08	100
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	SEQUENTIAL DECURRENCE REPORT NO. OOE TYPE NO.
	ACTION FUTURE CAPECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMPONENT MANUFACTURER SUPPLIER SUPPLIER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER SUPPLIER SUPPLIER MANUFACTURER SUPPLIER SU
[10]	Due to personnel error, maintenance personnel did not establish a fire watch as re-
	quired. This occurrence has been discussed with personnel involved. Fire doors
	controlled by procedure have been identified with signs on each side of the door.
	A copy of this LER will be routed to all mechanical maintenance personnel.
	ACILITY DISCOVERY DESCRIPTION 32 LE 28 0 9 9 9 29 NA ACILITY DISCOVERY DESCRIPTION 32 NA JA 31 Operator Observation
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 AMOUNT OF ACTIVITY 35 NA
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 1552 254
1 10	PERSONNEL INJURIES NUMBER DESCRIPTION 41 OLS OF DH DAMAGE TO FACILITY 43 PERSONNEL INJURIES DESCRIPTION 41 BO RESCRIPTION 41 BO RESCRIPTION 43
Ä	10 80
2 0	NRC USE ONLY NA NA NA NA NA NA NA NRC USE ONLY 10 NRC USE ONLY
	NAME OF PREPARER L. I. Lawrence PHONE 402-825-3811
	7912136 393