



CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: (con't.)

of the valves so that all 4 valves will close in the clockwise direction and open in the counter clockwise direction. This change will be completed by 7-15-79. The cause of this event was that the valve was not installed properly and it has been emphasized to the operators to perform "hands on" inspection of the valves and not to believe valve position indication only.

271 059