

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L J M F 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE: L 0 5 0 0 0 3 4 8 7 0 6 0 7 7 9 8 0 7 1 9 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | At 1020 on 6/7/79, radiation monitor R25A (Fuel Storage Pool Area, Gaseous Activity -
0 3 | Ventilation System Isolation) was declared inoperable due to pump failure. Tech. Spec.
0 4 | section 3.3.3.1 and table 3.3.6 requires a minimum of two radiation monitor channels
0 5 | to be operable for the fuel storage area. Tech. Spec. 3.3.3.1 action statement
0 6 | requirements were met. R25A was returned to an operable status at 1020 on 6/15/79.
0 7 | The health and safety of the public were not affected.

0 8 |

0 9 | B B 11 E 12 X 13 P U M P X X 14 H 15 Z 16

17 | 7 9 0 2 7 0 3 L 0
 ACTION TAKEN: A 12 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 V 1 1 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | This event is attributable to pump malfunction. The pump was repaired, belts
1 1 | replaced and the temperature overload devices reset. Following repair and verification
1 2 | of proper operation, R25A was declared operable at 1020 on 6/15/79.

1 3 |

1 4 |

1 5 | G 0 0 0 NA A 31 | Operator observation

1 6 | Z Z NA NA NA

1 7 | 0 0 0 Z NA

1 8 | 0 0 0 NA

1 9 | Z NA

2 0 | N NA

POOR ORIGINAL

368 178

7 907240 379

NRC USE ONLY