

PTP-QC-79-126
Turkey Point Plant
June 27, 1979

Mr. J. P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Atlanta, Georgia 30303

Mr. H. E. Yaeger, Plant Manager
Turkey Point Plant - DPR 31 and 41
Florida Power and Light Company
Miami, Florida

J. P. O'REILLY
M. UPRIGHT
D. CHENDEMI
B. KERRA
LONG
MURPHY
SUTHERLAND
BLANK
James Jenkins Webster

79 JUN 28 P 3: 45

USNRC REGION II
ATLANTA, OFFICE

CT: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM REPORTABLE OCCURRENCE 250-79-22

This memo confirms our telephone notification of the subject prompt notification table occurrence made Tuesday June 26, 1979, to Mr. Richard Messian of your office as follows:

DEFICIENCY - Review of our electrical system has revealed a unique situation where loss of 4160 volt bus would not result in automatic transfer of the shared D motor control to its alternate supply from the 4A 4160 volt bus. If a Unit 3 safeguards signal occurred during this situation, only one emergency containment cooler and one emergency containment filter would automatically start.

CORRECTIVE ACTION - Immediate corrective action will consist of instructions to actuate the D motor control center manually if this situation should arise. This action will be issued prior to return of Unit 3 to power operation. Long term corrective action will involve a design change to assure automatic transfer of the D motor control center under this circumstance.

H. E. Yaeger
H. E. Yaeger
Plant Manager

HT: sr

POOR ORIGINAL



309 165

*A002
5 1/0*

①

7907090 337 5