

DAE
M Collins

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: 215-337-5324
Telephone Number

Date/Time: July 16, 1979 / 0900

To: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35

Assigned LER Number 79-022/01X-0

Event Description: On July 13, 1979, while continuing our evaluation of seismic restraints, it was discovered that two pipe supports did not meet

the original design SSE specifications. These pipe supports are on the HPCI test line downstream of the test valve and on the RHR cross-tie.

Cause and Corrective Action: The cause of this event was design error.

Plant design changes requests were prepared and modifications are in progress to bring the supports up to standards.

Facility Status:

- c) Routine Startup _____
- d) Routine Shutdown _____
- e) Steady State _____
- f) Load Changing _____

- | | |
|-------------------|--------------|
| 0 | I Thermal MW |
| g) Shutdown | <u>X</u> |
| h) Refueling | _____ |
| i) Other | _____ |
| j) Not Applicable | _____ |

A written follow-up report will be sent within two weeks.

NRC person notified T. Stedka

Prepared by Charles J. Mathis

POOR ORIGINAL

7907200 275

A002
S. / 10

Mail (2) copies to:

Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

462 359