

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CLRSL 1000-1000000-00034111115
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

02 On July 20, 1979, B&W informed the District that additional small break
03 LOCA analyses have indicated that for a certain spectrum of small leaks in
04 the RCS coupled with loss of RCP's at some time later in the transient
05 could cause 10 CFR 50 Appendix K criteria to be exceeded.
06
07
08

09 CLB X 2 LP L P E X X E Z 17 79 12 0106 102 T 0
33 H 18 G 19 Z 20 Z 21 0900 X 23 N 24 N 25 8015 26
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

10 Additional analyses by all NSSS suppliers as a result of TMI-2. Corrective
11 actions will be done in accordance with the requirements of I&E Bulletin
12 79-05C and 79-06C.
13
14

POOR ORIGINAL

15 E 1100d NA D Notification from NSSS
16 Z Z NA NA
17 000 Z Z NA
18 000 Z NA
19 Z NA
20 N

NAME OF PREPARE: R. W. Colombo

PHONE: (916) 452-3211

7908100337

531 347