

DUKE POWER COMPANY
ELECTRIC CENTER, BOX 33189, CHARLOTTE, N. C. 28242

L. C. DAIL
VICE PRESIDENT
DESIGN ENGINEERING

JUN 27 A 9: 51

June 22, 1979

Mr. J. T. Sutherland, Chief
Fuel Facility and Materials Safety Branch
U. S. Nuclear Regulatory Commission, Region II
101 Marietta Street, N. W., Suite 3100
Atlanta, Ga. 30303

Re: Catawba Nuclear Station, Units 1 & 2
RII: ALC
50-413/79-4 and 50-414/79-4
File No: CN-1421.13


Dear Mr. Sutherland:

This refers to an inspection conducted by Mr. A. L. Cunningham on May 15-17, 1979 at Catawba Nuclear Station. In his report, one item of noncompliance was noted concerning the licensee's failure to provide adequate erosion control measures in the site construction area.

Your letter requested that a response, pursuant to 10CFR 2.201, be filed within twenty (20) days of receipt of the report. Following is Duke Power Company's response:

1. The northwest bank opposite the LPSW intake structure was ripped to effectively control erosion of the area.
2. No further corrective measures are required.
3. Full compliance was achieved May 25, 1979.

Yours very truly,



L C Dail

LCD/sc

cc: R L Dick
D G Beam
D B Packmon
W H Gasin

532 294

7908100383
COPY