



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

August 3, 1979

CYH 79-189

U. S. Nuclear Regulatory Commission  
Region 1  
Office of Inspection and Enforcement  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attn: Mr. Boyce Grier,  
Director

Reference: Facility Operating License No. DPR-61  
Docket No. 50-213  
Reportable Occurrence LER 79-08/1P

Dear Mr. Crier:

In accordance with the reporting requirements of Connecticut Yankee Technical Specifications, Section 6.9.2.(9), the following preliminary report 79-08/1P is hereby submitted.

While performing an inspection of seismic Category I piping systems as part of a program to verify operability which is required by IE Bulletin 79-02, Rev. 1, it was discovered that one pipe support on the residual heat removal system piping was not installed as per the design drawing. The investigation performed showed that the existing support does not provide proper seismic support. A support is currently being added to conform to original drawings and provide proper seismic support. This will be done within 72 hours.

A follow-up report will be submitted within fourteen (14) days.

Very truly yours,

Richard H. Graves  
Station Superintendent

RHG:JHF/jhb

cc: Dir., Office of Management Info. and Program Control, Wash., D. C. (2)

611 350

A002/10  
5/10

7908100438