

79008

## TELEPHONE REPORT

USNRG RE  
ANTA

LOCALITY: Phipps Bend

DOCKET #: 50-553, 554

DATE: 8/2/79

TIME: 10:00 AM

LIC. OCC. #: CDR PBN-033

SUBJECT: HPCS D/G Control Switch Gear Wiring Discrepancies

DESCRIPTION OF OCCURRENCE: While testing, the licensee identified several discrepancies between the as build circuits and the wiring diagrams supplied by the vendor, Morris Knudsen. A similar problem was previously reported with like equipment supplied for the Hartsville Plant (10 CFR 50.55(e) final report dated 3/7/79). This problem may be generic.

*J. S. Carbel*  
SIGNATURE

7908140545

B019  
S 0/1

627277

79097