



Facility: BSEP Unit No. 2

Event Date 7-10-79

with an apparent improper bleed rate. All mechanics performing snubber testing will be instructed in the proper method of reading the associated graphs and performing the associated tests. The next PT on visual inspection of accessible snubbers will include snubber 2E11-128SS427 in its total of failed snubbers to determine inspection frequency per Technical Specification.