ask-Hys



## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

2 5 MAY 1979

Docket No. 99900502/79-02

Brown and Root, Incorporated
ATTN: Mr. Thomas J. Feehan
President and Chief
Executive Officer
4100 Clinton Drive
Post Office Box 3
Houston, Texas 77001

## Gentlemen:

This refers to the QA program inspection conducted by D. G. Anderson of this office on May 7-11, 1979, of your facility at Houston, Texas and to the discussions of our findings with Mr. E. H. Bomke and members of your staff at the conclusion of the inspection.

Areas examined during the QA program inspection and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedure and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, we found no instance where you failed to meet the commitments of your Topical Report No. B&W-002A.

In accordance with Section 2.790 of the Commission's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter together with the enclosed inspection report will be placed in the Commission's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application within thirty (30) days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

7907230730

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Uldis Potapovs, Chief Vendor Inspection Branch

Enclosure: Inspection Report No. 99900502/79-02