

RO TELEGRAM FORMAT

01 BAXLEY, GA. 31513
PMS MR. JAMES P. O'REILLY
UNITED STATES NUCLEAR REGULATORY COMMISSION
DIRECTOR OF INSPECTION AND ENFORCEMENT
REGION II
SUITE 3100
101 MARIETTA STREET
ATLANTA, GEORGIA 30303

SUBJECT: HATCH UNIT I, DOCKET NO. 50-321, NOTIFICATION OF REPORTABLE OCCURRENCE
NO. 50-321/1979-55

DATE: 8-3-79

NOTIFIED: R. F. Rogers

DATE: 8-3-79
TIME: 2:45 PM EDT

DESCRIPTION OF REPORTABLE OCCURRENCE

Initial Condition

Relay coil on relay E11-K126 in panel H11-P618 was found to not energize while performing HNP-1-3153-E.

Nature of Occurrence

Cause still under investigation.

Immediate Corrective Action

MR was written to replace relay. Relay was then tested with acceptance.

Cause

Component failure

Supplemental Corrective Action

Relay (New One) was checked, installed and HNP-1-3153-E was completed.

Status of Redundant or Backup Systems

Since both loops of RHR were in service, three other RHR pumps were available if they had been needed.

Impact to Other Unit

None


018023

A002
S 1/1

790813047C

Justification for Continued Operation

Relay replaced, system restored to original functional status.


M. Manry
Plant Manager

618024