

Appendix A

NOTICE OF VIOLATION

Refinery Products Corporation

License No. 48-03665-02

As a result of the inspection conducted on January 7, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10 CFR 20.401(b) requires each licensee to maintain records showing results of surveys required by 20.205(b), "Procedures for picking up, receiving and opening packages."

Contrary to the above, no record of results of package surveys of an incoming Ir-192 source were maintained.

This is a Severity Level VI violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within twenty-five days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

1/16/81
Dated

W. L. Fisher
W. L. Fisher, Acting Chief
Fuel Facility and Materials
Safety Branch

8102240024