

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

April 30, 1979

J. T. HEAD, JR.
VICE PRESIDENT

TELEPHONE
213-572-1472

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
Walnut Creek Plaza, Suite 202
1990 North California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken,
Director

Docket 50-206
San Onofre Unit 1

Dear Sir:

IE Bulletin No. 79-04
Incorrect Weights for Velan Swing
Check Valve

The subject IE Bulletin was forwarded to Mr. J. B. Moore with your letter dated March 30, 1979.

The response to the items in the referenced IE Bulletin No. 79-04 are listed below.


Item 1 List all Seismic Category I piping systems (or portions thereof) where 3, 4, or 6 inch diameter Velan swing check valves are installed or are scheduled to be installed.

Response:

Detailed investigation of system's components has disclosed that at SONGS 1 there are no Velan swing check valves installed on any system.

The response to Item 1 nullifies the applicability of Items 2 through 6.

Sincerely,



cc: Director, Office of Inspection and Enforcement,
Division of Reactor Operations Inspection

7907050413

281 110