

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8
---	---

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

14 corrosion, causing the F012 valve to not fully close. (CON'T)

7 8 9 10 PUBLICITY ISSUED — DESCRIPTION (45) NRC USE ONLY 30

NRC USE ONLY

PHONE: 919-457-9521

Facility: BSEP Unit No. 2

Event Date: 7-21-79

The pressure switch was replaced, calibrated, and its conduit entrance was resealed to prevent moisture damage. The valve was then tested satisfactorily. The switch on the Unit 1 HPCI unit was inspected and found to be satisfactory. This is considered an isolated event and no further action is required.