


## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137



JUL 1 6 1979

Midwest Inspection Services, Inc. ATTN: Mr. Donald Paschen 957 Mancel Lane Green Bay, WI 54304

License No. 48-16296-01

## Gentlemen:

This refers to the inspection conducted by Mr. W. H. Schultz of this office on June 6, 1979, of activities authorized by NRC Byproduct Material License No. 48-16296-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

JUL 1 6 1979

Midwest Inspection Services, - 2 - Inc.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

A. B. Davis, Chief Fuel Facility and Materials Safety Branch

Enclosure: Appendix A, Notice of Violation

cc w/encl: Central Files Reproduction Unit NRC 20b PDR NSIC