



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 12, 1979

2-099-6

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/79-070; 50-368/79-071;  
50-368/79-072; and 50-368/79-073  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning the failure of a battery eliminator causing two Reactor Trip Breakers to open rendering one channel inoperable per Technical Specifications (50-368/79-070); the failure of the "B" Core Protection Calculator causing low DNBR and high LPD trips in the "B" PPS (50-368/79-071); the tripping of the Emergency Feedwater pump turbine driver (50-368/79-072); and the placement of all CEA Calculator inputs to the CPC's in an inoperative mode for diagnostic testing of CEAC outputs (50-368/79-073).

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:REI:pw

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management & Prog. Analysis  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. D. Johnson  
U.S. Nuclear Regulatory Commission  
P. O. Box 2090  
Russellville, Arkansas 72801

364354

7909180 488 J