

AUG 9 1979

NOTE TO: R. Vollmer, Assistant Director for Systematic Evaluation Program,
Division of Operating Reactors

THRU: G. Lainas, Chief, Plant Systems Branch, Division of Operating
Reactors

FROM: M. Chiramal, Plant Systems Branch, Division of Operating
Reactors

SUBJECT: COMMENT ON ELECTRICAL EQUIPMENT INSIDE CONTAINMENT OF TMI-2

REFERENCE: Equipment List attached to GPU Letter dated July 19, 1979

Any equipment that may be rendered inoperable by flooding should be traced to its electrical power source (an instrument power supply bus, distribution panel, motor control center or switchgear). At the first sign of a malfunction attributable to flooding, the equipment should be electrically isolated at the power source so as to prevent propagation of failure to other equipment connected to the same source.

M. Chiramal,
Plant Systems Branch
Division of Operating Reactors

cc: G. Lainas
D. Tondi
J. T. Beadd
M. Chiramal
LOCAL PDR
Hdgtrs, PDR

REGULATORY WORK FILE COPY

1002 041

OFFICE	DOR:PSB <i>llc</i>	DOR:SL-PSB	DOR:PSB		
SURNAME	MChiramal LL	DTondi <i>BT</i>	GLainas		
DATE	8/9/79	8/9/79	8/9/79		