## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
_	CONTROL BLOCK: (PLEAS! PRINT OR TYPE ALL REQUIRED INFORMATION)
0	1   C   0   F   S   V   1   2   0   0   -   0   0   0   0   -   0   0
0	1 REPORT L 6 0 5 0 0 0 2 6 7 7 0 9 1 0 7 9 8 1 10 1 0 7 9 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0	3 to be missing a pin at the piston rod eye, and was thus inoperable. This is operation
0	in a degraded mode of LCO 4.3.10 and is reportable per Fort St. Vrain Technical Speci-
0	fication AC 7.5.2(b)2. No affect on public health or safety.
0	[6]
0	7
0	8 9
0	SYSTEM CAUSE SUBCODE S
	COMPONENT   COMP
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1	One cold reheat snubber was inoperable due to a missing pistop rod eye.pin. A new
1	pin was fabricated and installed. The surveillance interval is presently 12 months
	12 ± 25%. No adjustment is required.
1	[3] L
7	[4] L 8 9
_	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  5 G 28 0 0 0 0 29 N/A A A 31 Personnel Observation
1	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  [6] [Z] 33 [Z] 34 N/A N/A
1	8 9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  7 0 0 0 37 Z 38 N/A
7	8 9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41  1 1 5 4 1 4 3
7	8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION  19   Z   (42)   N/A
7	9 10 PUBLICITY ISSUED DESCRIPTION (45)  O NAC USE ONLY  O NAC USE ONLY  O NAC USE ONLY
7	NAME OF PREPARER (303) 785-2253
	THOUSE ALL THE PARTY OF THE PAR