404045.9.94HE8V32.0. #8.9.0170.9.0HE42



THE CONTROL BOOKEN OF AND THE HOUSE CANDON
THE SHART CHARGES THE CONTROL OF THE CONTROL
WITH SHART CHARGES THE SHART CHARGES
HAVE AN WORKEN PROBLEM CHARMS
IN THIS ACCOUNT OF THE CONTROL
TO CONTROL OF THE CONTROL OF THE CONTROL
THE CONTROL OF THE

P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

November 2, 1979 MP-2-4183

Mr. Boyce H. Grier Director, Region I Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336 LER 79-28/3X-1

Dear Mr. Grier:

This letter forwards update Licensee Event Report 79-28/3X-1 submitted pursuant to Millstone Unit 2 Technical Specifications, Section 6.9.1.9.b. The report concerns conditions leading to operation in a degraded mode permitted by a limiting condition for operation. An additional three copies of the report are enclosed.

Yours truly,

J.F. Opeka

Station Superinter dent

Millstone Nuclear Fower Station

JFO/ECF:kat

Attachment:

LER 79-28/3X-1

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30) Director, Office of Management Information and Program Control,

Washington, D.C. (3)

1292 179