TENNESSEE VALLEY AUTHORITY

716 Edney Building

November 13, 1979

Mr. James P. O'Bailly, Director U.S. Muclear Bagulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TERMESSEE VALLEY AUTHORITY - BROWNS FERRY BUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFRO-50-259/7829

The enclosed report is a supplement to the letter from H. S. Fox dated October 25, 1978, concerning the cable receway between the dissel generator building and the standby gas treatment building which appeared to have settled two inches at the dissel generator building end expansion joint during normal operation while installing additional cables. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.a(9).

Very truly yours,

TERRESSEE VALLEY AUTHORITY

POOR ORIGINAL

J. R. Calhoun Director of Nucle : Power

Enclosure (3) cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Huclear Regulatory Commission
Washington, DC 20555

L. F. Salliven, MRC Inspector, Browns Ferry

1347 004

A003/