LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 -1 7 8	C G F S V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 6 7 7 1 0 1 1 7 9 8 1 1 0 9 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Con October 11, 1979, it was determined that due to procedural inadequacies, a parti-
0 3	cular sequence of manual switching of the primary coolant low level dew point moisture
_	monitors could have resulted in a degraded mode of LCO 4.4.1. This is reportable per
0 4	
0 5	Fort St. Vrain Technical Specification AC 7.5.2(b)3.
0 6	
0 7	
0 8	SYSTEM CAUSE CAUSE COMP. VALVE
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	17 REPORT NO. REPORT NO. CODE TYPE NO. LER RO 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NORD-4 PRIME COMP. SUPPLIER MANUFACTURER G 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 N 25 G 0 6 3 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	An approved field change notice (FCN 3738B) made the automatic trip on moisture
11	monitor system failure a manual action and revised the logic to allow individual
1 2	moisture monitors to be tripped (rather than disabling by pairs). However, if the
1 3	correct switching sequence was not followed it was possible to lock out a moisture
1 4	monitor inadvertently. The system opprating procedure was revised to prevent this
7 8	9 from occurring. No further corrective action is anticipated or required. FACILITY STATUS 90 DISCOVERY DISCOVERY DISCOVERY DISCOVERY DESCRIPTION (32)
1 5	E 28 0 6 0 29 N/A A Instrument Personnel Observation
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 11 12 13 13 13 13 13 10 10 10 10 10 10 10 10 10 10 10 10 10
	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	0 0 0 40 N/A 9 LOSS OF OR DAMAGE TO FACILITY (43) 1343 187 80
1 9	Z 42 N/A
2 0	PUBLICITY ISSUED DESCRIPTION (45) N/A 7911190386 NRC USE ONLY
7 8	9 10 NAME OF PREPARER J. W. Gahm PHONE: (303) 785-2253