

TELECOPY SENT Received
Verified Receipt: 12/29/78
Date 12/29/78
Time 11:51 hours
Initials Cjm

December 29, 1978

TO: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III

Attention: Tom Tambling

SUBJECT: Reportable Occurrence Per Technical Specification 6.9.8.f

Davis-Besse Unit 1 Mode 4, Power (MWT) = 0 and Load (MWE) = 0

During startup operations on December 28, 1978, the unit entered Mode 4 at 1720 hours. At 1930 hours, both Containment Spray Pump Motor Breakers were found to be racked out. The heatup was immediately stopped, and the breakers were racked in at 2025 hours. The apparent cause of this event was personnel error. Further investigation is in progress.

T. Tambling, NRC Region III, notified via telephone at 1000 hours on December 29, 1978.

Terry D. Murray/SJS

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station
Toledo Edison Company

TDM/JRL/ljk

50-34p

7901160161

*A002
5/10
S*