License No. DPR-50

## APPENDIX A

## NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on September 21-23, 1977, it appears that two of your activities were not conducted in full compliance with conditions of your NRC Facility License No. DPR-50 as indicated below.

A. 10 CFR Part 50, Appendix B, Criterion XVI states: "Measures shall be established to assure that conditions adverse to quality, such as... malfunctions...are promptly identified and corrected."

The licensee subscribed to 10 CFR Part 50, Appendix B, in Paragraph 20 of Appendix 1A of his Final Safety Analysis Report.

In the same paragraph, it states: "...nonconformance such as equipment malfunction...at the station are identified and resolved."

Contrary to the above, the ventilation fan B in the battery rooms was inoperable.

This item is an infraction.

B. 10 CFR Part 50, Appendix B, Criterion V states: "Activities affecting quality shall be prescribed by documented instructions...and shall be accomplished in accordance with these instructions...."

The licensee subscribed to 10 CFR Part 50, Appendix B, in Paragraph 10 of Appendix 1A of his Final Safety Analysis Report.

In the same paragraph, it states: "...instructions...associated with the administration...of structures...are...implemented...."

The door to the cable spreading room is posted with a "No Smoking" sign.

Contrary to the above, numerous cigarette butts were found on the floor of the cable spreading room.

This item is an infraction.

1450 052

7910170 741