

ENCLOSURE
DESCRIPTION OF VIOLATIONS

Metropolitan Edison Company
Eocket No. 50-289
License No. DPR-50

One activity under your license which appears to be in violation of AEC regulations, is considered to be of Category II severity.

1. Technical Specification 2.3.2.A.2, Appendix B requires that the Auxiliary and Fuel Handling Building exhaust gas, iodine and particulate monitor, RM-A8 or similar device shall be operable during release of gaseous waste from the gas decay tanks.

Contrary to the above, the iodine monitoring channel on RM-A8 was removed from service, for approximately thirty-five minutes, on September 28, 1974 during a gaseous release from a gaseous waste decay tank. We note that this was reported in your letter, dated, October 4, 1974. It is further noted that implementation of corrective and preventive action identified in that letter was verified during the inspection.

A second activity under your license which appears to be in violation of AEC regulations is considered to be of Category III severity.

2. Technical Specification 4, Table 4.1-1, Appendix A and Technical Specification 2.3.1 and 2.3.2, Appendix B requires that certain radiation monitoring systems shall be calibrated at quarterly intervals.

Contrary to the above, quarterly calibrations, due to be completed by June 30, 1974, were not accomplished until approximately two months after that date. We note that this was reported in your letter, dated, September 26, 1974. It is further noted that corrective and preventive actions identified in that letter were verified during the inspection.

1453 279

7910180733