PO BOX 270 HANTFORD, CONNECTICUT 05101 (203) 655-6711

POOR

ORIGINAL

October 10, 1978

MP-1-992

Mr. Boyce H. Grier Director, Region I Office of Inspection and Enforcement U. S. Muclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference: Provisional License DPR-21 Docket No. 50-245 Reportable Occurrence R0-78-20/1P

Dear Mr. Grier:

This letter is forwarded to provide prompt notification of Reportable Occurrence RO-78-20/IP as required by the Hillstone Unit I Technical Specifications.

On October 10, 1978, at 0920 hours, during normal plant operation, it was discovered that the unused chloride capacity of one of the full flow on line demineralizers was less than the 30 pound minimum prescribed in Technical Specification 3.6.J.I. Unit power was immediately reduced and the demineralizer was removed from service. Results of the investigation into the incident and further analysis will be included in the follow up 14 day report.

Yours truly,

50-245

J. F. Opeka Station Superintendent Millstone Ruclear Power Station

JFO/RHY/JJ

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30) Director, Office of Management Information and Program Control, Washington, D.C. (3)

7906040353