LICENSEE EVENT REPORT

6	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C O F S V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58 5
CON'T 0 1 3	SOURCE L 6 0 5 0 0 0 2 6 7 7 0 1 1 0 8 0 8 4 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On January 10, 1980, with the reactor in a shutdown condition, 3 hangers were found
013	impaired, which caused the 21 system to be impaired. The 3 hangers were 11A-H-21235,
	1 11A-H-21236, and 11A-H-21237. This is a degraded mode of LCO 4.3.10 and is reportable
0 4	
0 5	per Fort St. Vrain Technical Specification AC 7.5.2(b)2. There was no affect on
0 6	public health or safety. Similar to Reportable Occurrence Report No. 79-58.
0 7	
7 3	9
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUBMITTED FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 O O O O D Y 23 N 24 A 25 X 9 9 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	Cause of System 21 impairment was impairment of 3 hangers, 11A-H-21325, 11A-H-21326,
. 111	and 11A-H-21327. These hangers were removed for a system modification and were not
1 2	re-installed. Change Notice 1178 will modify and re-install these hangers.
1 3	
7 8	1 90
1 5	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 D 28 0 0 0 29 N/A C 31 Engineering Analysis of Hangers
1 6	ACTIVITY CONTENT 12 13 AMOUNT OF ACTIVITY 35 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A 12 13 AMOUNT OF ACTIVITY 35
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A
7 8	PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 0 0 0 0 0 0 0 0 0 1 0 0 0 0 0 0 0 0 0
19	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 8 0 21 2 0 7 2 4
20	PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
	NAME OF ROSALOFO 1/4 His him - 2005 (303) 785-2253