

Appendix A

NOTICE OF VIOLATION

Union Electric Company

Docket No. 50-483

Based on the results of an NRC inspection on November 14-16, 1979, it appears that one of your activities is in noncompliance with NRC requirement as noted below. This item is considered an infraction.

10 CFR 50, Appendix B, Criterion III states, in part, that "Measures shall be established to assure that applicable regulatory requirements and the design basis . . . are correctly translated into specifications, drawings, procedures, and instructions."

Design drawing EOR-8900 Revision 9 paragraph 2.12 states, "Trays will be joined with splice plates and hardware according to tray manufacturer's recommendations."

P-W Industries, the cable tray manufacturer in a letter dated August 14, 1979 recommended "Tapping the bolt head with a hammer, finger threading the nut, then tighten to a maximum of 30 foot pounds torque.

Contrary to the above, the inspectors determined that the manufacturer's recommendations to ensure that cable trays are adequately joined were neither translated in cable tray installation procedure WP302 nor inspection procedure QCP302.