



LER CONTINUATION -- RO# 1-79-035

Facility: BSEP Unit No. 1

Event Date: 5-17-79

in the instrument air system. This item was not reported originally due to an administrative oversight. It was originally thought that the control switches were the only problem. This by itself would not be reportable as the valves would still isolate on a proper signal. Those involved with the review of LCO's have been counseled to obtain the complete problem description before determining reportability.

2286 118