

USNRC REGION II
DUKE POWER COMPANY
ATLANTA, GA
POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

19 MAY 11 AIO: 45

May 8, 1979

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: RII:RJH
50-369/79-11

Dear Mr. O'Reilly:

As requested by Mr. C. E. Murphy's letter of April 11, 1979 a supplemental response to IE Inspection Report No. 50-369/79-11 follows:

Since our initial response to IE Inspection Report No. 50-369/79-11 dated April 2, 1979, the damaged cable has been meggered and indicated an apparent failure of one conductor. A shutdown request was issued and subsequently the cable replaced on May 3, 1979. This action was documented on Nonconforming Item Report No. 8753.

Very truly yours,



William O. Parker, Jr.

GJP:scs

2210 353

7906250/70 Q
790141
OFFICIAL COPY