

FEB 16 1972

E. G. Arndt, Structural Engineering Branch, DRS
F. P. Schauer, Structural Engineering Branch, DRS
R. E. Shewmaker, Structural Engineering, Branch, DRS

CONSTRUCTION PROBLEM: REPAIR OF REINFORCING BARS
THREE MILE ISLAND NUCLEAR STATION UNIT 1, DOCKET No. 50-289

On February 16, 1972, Dr. A. Gluckmann had a telephone conversation with Dr. C. P. Siess on the repairs of the ring girder for the Three Mile Island Nuclear Station Unit 1. Dr. C. Siess expressed his concern about repairing damaged reinforcing bars by welding as it may result in high stress concentrations.

Dr. Siess suggested that this repair practice be avoided and prohibited.

L. C. Shao

L. C. Shao
Structural Engineering Branch
Division of Reactor Standards

cc: R. R. Maccary, DRS
A. L. Gluckmann, DRS

Distribution:
Suppl. 50-289
DRS RF
SEB RF

1486 056

OFFICE ▶	DRS:SEB								
SURNAME ▶	<i>Shao:ewe</i>								
DATE ▶	2- -72								

7910180573

A