

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: _____ ①

⑦ ⑧ ⑨ | A | L | B | R | F | I | ② | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | ③ | 4 | 1 | 1 | 1 | 1 | ④ | _____ | ⑤
7 8 9 14 15 25 26 30 37 38
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
⑦ ⑧ ⑨ | L | ⑥ | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 9 | ⑦ | 0 | 1 | 1 | 2 | 8 | 0 | ⑧ | 0 | 2 | 0 | 8 | 8 | 0 | ⑨
7 8 9 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

⑦ ⑧ ⑨ | ⑦ | While unit 1 was shutdown for refueling, wind direction channel at 33 feet elevation
⑦ ⑧ ⑨ | ③ | as observed on wind direction recorder XR-90-102-2 failed upscale (T. S. 3.2.I). Wind
⑦ ⑧ ⑨ | ④ | direction indicators at 150 feet and 300 feet elevations were operable. There have
⑦ ⑧ ⑨ | ⑤ | been no previous failures of this nature. There was no danger to the public health
⑦ ⑧ ⑨ | ⑥ | or safety. There are no redundant systems.

⑦ ⑧ ⑨ | _____ | 80

⑦ ⑧ ⑨ | I | E | ⑪ | E | ⑫ | E | ⑬ | I | N | S | T | R | U | ⑭ | E | ⑮ | Z | ⑯ |
9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

⑦ ⑧ ⑨ | ⑰ | 8 | 0 | ⑱ | 0 | 0 | 2 | ⑲ | 0 | 3 | ⑳ | L | ㉑ | 0 |
21 22 23 24 26 27 28 29 30 31 32
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN ⑳ | B | ㉑ | Z | ㉒ | EFFECT ON PLANT ㉓ | Z | ㉔ | SHUTDOWN METHOD ㉕ | Z | ㉖ | HOURS ㉗ | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED ㉘ | Y | ㉙ | NPRD-4 FORM SUB. ㉚ | N | ㉛ | PRIME COMP. SUPPLIER ㉜ | L | ㉝ | COMPONENT MANUFACTURER ㉞ | A | 0 | 4 | 2 |
33 34 35 36 37 40 41 42 43 44 47
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

⑦ ⑧ ⑨ | ⑰ | The series 312D millivolt to current converter was repaired and returned to service in
⑦ ⑧ ⑨ | ⑱ | five hours. The indicator failed due to lightning damage at the meteorological tower.
⑦ ⑧ ⑨ | ㉑ | No recurrence control action is planned since the incident is considered random in
⑦ ⑧ ⑨ | ㉒ | nature.

⑦ ⑧ ⑨ | _____ | 80

⑦ ⑧ ⑨ | H | ㉓ | 0 | 0 | 0 | ㉔ | OTHER STATUS ㉕ | NA | METHOD OF DISCOVERY ㉖ | A | ㉗ | Observed by operator. ㉘ |
7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

⑦ ⑧ ⑨ | Z | ㉙ | Z | ㉚ | NA | AMOUNT OF ACTIVITY ㉛ | NA | LOCATION OF RELEASE ㉜ |
7 8 9 10 11 44 45 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

⑦ ⑧ ⑨ | 0 | 0 | 0 | ㉝ | Z | ㉞ | NA | DESCRIPTION ㉟ |
7 8 9 10 11 12 13 44 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

⑦ ⑧ ⑨ | 0 | 0 | 0 | ㊱ | NA | DESCRIPTION ㊲ |
7 8 9 10 11 12 13 44 80
PERSONNEL INJURIES NUMBER DESCRIPTION

⑦ ⑧ ⑨ | Z | ㊳ | NA | DESCRIPTION ㊴ |
7 8 9 10 11 12 13 44 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

⑦ ⑧ ⑨ | Z | ㊵ | NA | DESCRIPTION ㊶ |
7 8 9 10 11 12 13 44 80
PUBLICITY ISSUED DESCRIPTION

⑦ ⑧ ⑨ | N | ㊷ | NA | _____ | 80
7 8 9 10 68 69 80
NAME OF PREPARER

PHONE: 8002140585

POOR ORIGINAL

PER SUPPLEMENTAL INFORMATION

DC 90-102-259 / 802 Technical Specification Involved 3.2.I.

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 1/12/80 Time of Occurrence 0001 Unit 1

Identification and Description of Occurrences:

Wind direction recorder XR-90-102-2 was found to be indicating at full scale by operations personnel.

Conditions Prior to Occurrence:

- U-1 refueling.
- U-2 operating at 851 MWe.
- U-3 cold shutdown.

Are there any items in the Technical Specification Surveillance Requirements met due to inoperable equipment? Describe

None

Apparent Cause of Occurrence:

Lightning

Analysis of Occurrence:

There was no damage to other plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

Repaired the millivolt to current converter.

Further Data:

None

Officer: [Signature] - Lifeline: Responsibility - Administrative Supervisor

Notes:

[Handwritten signature]