

SEABROOK STATION
Engineering Office:
20 Turnpike Road
Westborough, MA 0158

October 27, 1978

SB-6830 T.F. Q 2.5.3

United States Nuclear Regulatory Commission Office of Inspection and Enforcement 631 Park Avenue King of Prussia, Pennsylvannia 19406

Dear Sir:

Design Deficiency

Enclosed is a report submitted under 10 CFR 50.55a (e), describing a design deficiency associated with the Seabrook Station Refueling Water Storage Tank.

Please let us know if you have any questions.

Very truly yours,

Wendell P. Johnson Vice President

tla

cc: 3.3. Beckley

J.H. Herrin

G.F. Cole

W.E. Wright

7511090147

305/1