

Vepco

REGION II
MARIETTA, GEORGIA

VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND, VIRGINIA 23261

TELEPHONE 36

December 20, 1978

TERA

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 661A
PSE&C/CGC/mac:wang

Docket No. 50-339


Dear Mr. O'Reilly:

In accordance with 10CFR50.55(e), the NRC, Region II, was notified on November 20, 1978 that spare containment pipe penetrations are not sealed at both ends as stated in the FSAR Section 6.2.4.3, Subsection 4, Page 6.2-125.

We have determined that there are 29 spare penetrations all of which have a welded cap on the inside containment end only.

Our engineering evaluation to determine the best corrective action is still in progress. This 30-day report shall be considered an interim report. A final report documenting the measures to be taken will be submitted by February 1, 1979.

Very truly yours,


Sam C. Brown, Jr.
Vice President - Power Station
Engineering and Construction

cc: Mr. John G. Davis, Acting Director
Office of Inspection & Enforcement

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation

7901250/88

780060

OFFICIAL COPY