

The Foxboro Company Foxboro, Massachusetts, U.S.A. 02035 • Telephone (617) 543-8750

April 20, 1979

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attention: Mr. Karl V. Seyfrit, Director

Subject: Response to your letter dated March 30, 1979.

Gentlemen:

Reference: Docket #99900297/79-01

The additional information requested in your letter of March 30, 1979 relative to your item B of the letter (Notice of Diviation) contained in your letter dated February 3, 1979 is as follows:

Finding B: "Several preinsulated terminals exhibited damaged insulation which exposed metal."

Corrective Action: Quality Control performed a 100% inspection of the terminals on sales order 76N-60795F and marked are damaged terminals which required re-placement.

Manufacturing performed rework of these terminals during week 6, 1979 (Feb. 5-9) and Quality Control performed a re-inspection week 7, 1979.

Preventative Measures: Systems Operations Quality Assurance to conduct audits of this item in the future.

Additional: Personnel assigned to this task have been prohibited from using battery or pneumatic powered screw drivers on the assembly and check out floor. All power operated screw drivers have been banned from the area.

We believe this additional information will be adequate for you to complete your review.

Very truly yours,

THE FOXBORO COMPANY

J. H. Leathers
J. H. Leathers

7906060075

cmb

cc: Dept. 110, J. W. Graham
Dept. 107, D. P. Aiken

Dept. 101, G. A. Rosica

Attachment

FOXBORO

2265035