



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

SUITE 202, WALNUT CREEK PLAZA 1990 N. CALIFORNIA BOULEVARD WALNUT CREEK, CALIFORNIA 94:56

May 18, 1979

## SUBJECT: EXXON NUCLEAR COMPANY DOCKET NO. 70-1257

Please replace the cover sheet you now have to the subject report with the attached. The report number has been changed from 70-1257/79-01 to 70-1257/79-04.

Also, please correct the second page of the letter to Exxon dated March 16, 1979 transmitting the report to reflect the new  $\underline{04}$  report number rather than  $\underline{01}$ .

Thank you.

Fuel Facility and Materials Safety Branch

2133 357

7906260 576

## U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

## REGION V

Report No. 70-1257/79-04

1 40 1

----

Docket No.	70-1257 License No. SNM-1227	Safeguards Group
	Exxon Nuclear Company	
	2101 Horn Rapids Road	
	Richland, Washington 99352	
Facility Na	ame: Richland Facility	
Inspection	at: Richland, Washington	
Inspection	Conducted: February 12-16, 1979	
Inspectors	: <u>Ilaini 9. Colui</u> W. J. Cooley? Fuel Facilities Inspector	 Date Signed
	W. J. Cooley? Fuel Facilities Inspector 71. 7. Guly	3/6/79
	P. R. Zurakowski, Radiation Specialist	Date Signed
Approved B	v: F.a. Wenslawski	3/16/79
1	for H. E. Book, Chief, Fuel Facility and I Safety Branch	Materials Sale orginal

Summary:

## Inspection on February 12-16, 1979 (Report No. 70-1257/79-01)

Areas Inspected: Organization; modifications and changes to facilities and systems; internal review and audit; safety committee activities; employee training programs; preventive maintenance/calibrations; operations review; criticality safety; emergency planning/fire protection; radiation protection; and confirmatory measurements. The inspection involved 58 inspector-hours onsite by two inspectors.

Results: No it ms of noncompliance or deviations were identified.

. IE:V Form 219 (2

2133 358