LICENSEE EVENT REPORT
CONTROL BLOCK:
0 1 P A B V S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58
CONT REPORT L
At 0400 hours, operating personnel attempted to start the containment sump pumps.
Neither pump would operate and they were declared inoperable at 0500 hours. The
old station, as the result of a reactor trip on 1/3/79, entered Operational Mode 5 at
[0]5 1005 hours on 1/4/79. The pumps were returned to operable status on 1/7/79.
06
07
7 8 9
SYSTEM CODE CAUSE CAUSE COMPONENT CODE SUBCODE
LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT TYPE NO. 17 REPORT 7 8 0 6 6 0 0 3 L 0 0
ACTION FUTURE EFFECT SHUTDOWN HOURS (22) SUBMITTED FORMSUB. SUPPLIER MANUFACTURER
DBZ 9 Z 20 DOOD N 23 LY 24 A 25 A 5 9 0 3
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The A containment sump pump was inoperable due to a misadjusted impeller. The
B containment sump pump was inoperable due to bad bearings. The A pump was
readjusted and the B pump was replaced with a new pump. The pumps were
satisfactorily ret ned to service.
7 8 9
STATUS STATUS OTHER STATUS
ACTIVITY CONTENT 12 13 44 45 46 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 6 Z 33 Z 34 N/A
1 7 0 0 0 37 Z 38 N/A
PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 N/A
LOSS OF OR DAMAGE TO FACILITY 43
1 9 Z 42 N/A
PUBLICITY 15SUED DESCRIPTION (45) N/A
7 8 9 10
NAME OF PREPARER J. A. Werling PHONE: 412-643-1258