

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

8005071134

Region I

Report No. 80-01

Docket No. 30-10458

License No. 19-16125-01 Priority _____ Category _____

Licensee: Savoy Construction Company

1109 Spring Street

Silver Springs, Maryland 20910

Facility Name: _____

Inspection at:

Inspection conducted:

Inspectors: C. A. Rowe
C. A. Rowe, Radiation Specialist

3-24-80

date signed

date signed

date signed

Approved by: H. W. Crocker
H. W. Crocker, Acting Chief, Materials
Radiological Protection Section, FF&MS Branch

3/28/80
date signed

Inspection Summary:

Telephone inquiry conducted January 9, 1980

Areas Covered: Expiration of license, disposal of licensed material.

Results: The Region I office has determined that this license should be retired.

DETAILS

1. Persons Contacted

Mr. Edilio Ursini

2. Expiration of License

The inspector contacted the licensee on January 9, 1980 and notified him that his license 19-16125-01 had expired on June 30, 1979. The licensee informed the inspector that he wished to terminate his license and retain the material for use only in the State of Maryland. The licensee stated he was applying for renewal of his Maryland possession license.

3. Evaluation by the Regional Office

The inspector contacted Mr. Brisson, Division of Radiation Control, State of Maryland and was informed that the licensee had applied for renewal of his possession license in the State of Maryland. Mr. Brisson stated the application was not approved due to lack of a qualified R.P.O. or users. On February 28, 1980, the State of Maryland impounded the byproduct material and placed it in storage at the University of Maryland College Park Campus. The byproduct material will remain in the possession of the State of Maryland, Division of Radiation Control until the licensee meets the requirements for a possession license and is granted a license by the State of Maryland.

Region I has evaluated the information supplied by the licensee and the State of Maryland, Division of Radiation Control and has determined that this license should be retired.