

APPENDIX A

NOTICE OF VIOLATION

License No. DPR-50

Based on the results of the NRC inspection conducted on July 7-9 and 12-15, 1976, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC Facility License No. DPR-50 as indicated below. This item is an Infraction.

- A. Technical Specification 3.5.2.4.d requires the core power quadrant tilt to be monitored at a minimum frequency of two hours, when core power exceeds 15 percent of rated power.

Contrary to the above, the core quadrant tilt was not monitored between 2303 on 5/26/76 and 0120 on 5/27/76 when the core power was above 15 percent of rated power.

One Deficiency identified through your internal audit program and for which corrective action was initiated is set out in the inspection report. No additional information is needed for this item at this time.

1413 148

7910150 321 321