LICENSEE EVENT REPORT

EVHIDIT

	EVUIDIT W
	CONTROL BLOCK []]] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	A R A N O 2 2 O O - O O O O O O O
O 1	SOURCE L 16 0 15 10 10 10 13 6 8 0 10 1 12 8 7 9 (8) 10 2 2 7 7 9 9
0 2	During Power Escalation Testing, steady state Mode 1 operation, CPC "D"
[0]3]	[failed. Channel "C" failed while CPC "D" was in test. Both resulted
0 4	[in DNBR and LPD trips in their respective PPS channels. Channels "C" &
0 [5]	"D" were declared inoperable and appropriate trips were bypassed. Similar
0 6	lto LER 50-368/79-011 and 79-006. Reportable per T.S. 6.9.1.9.(b).
0 7	
0 8	
0 9 3 8	SYSTES CAUSE SUBCODE COMPONENTS OF RULE SUBCODE SUBCOD
	17 REPORT VEAR SEQUENTIAL REPORT OF CODE 1 VERY SILVE OF THE PROPERTY OF CODE 1 VERY SILVE OF THE PROPERTY OF
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2) [CPC "D" failure was caused by the Channel DC power supply which tripped.
	The DC Power Supply was replaced. The channel "C" failure was unrelated
1 7	to the "D" failure. The channel "C" failure appears to be a non-repetitive
113	Lfailure. Both CPC channels were successfully restarted. The require-
1 4	ments of Action Statement T.S. Table 3.1-1 #2 were met.
	ACIENTY SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) B (38) [0 [1 9] [29] PWT.ESC. Test A (31) NA
	CHIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
17	O O O O O O NA
T R	PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
1 9	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 10
2 0	
	NAME OF PREPARER Chris N. Shively 501/968-2519