

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	G	A	E	I	H	2	2	0	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	1	1	4			5					
8	9	LICENSEE CODE					14	15	LICENSE NUMBER												25	26	LICENSE TYPE					30	57	CAT	58					

REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 1 1 1 7 9 8 0 1 2 4 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

With the unit in cold shutdown while performing HNP-2-3410, RCIC Steam Line Differential Pressure FT&C, the low switch of 2E51-N018 operated at -141" H₂O and the High Switch operated at +160" H₂O. The Technical Specification Limits are ≥ -133 " H₂O for the low switch and $\leq +133$ " H₂O for the high switch. These limits correspond to $\leq 300\%$ of rated flow.

SYSTEM CODE I B (1)		CAUSE CODE X (2)		CAUSE SUBCODE Z (3)		COMPONENT CODE I N S T R U (4)				COMP SUBCODE S (5)		VALVE SUBCODE Z (6)	
10		11		12		13				14		15	
16		17		18		19				20		21	
22		23		24		25				26		27	
28		29		30		31				32		33	
34		35		36		37				38		39	
40		41		42		43				44		45	
46		47		48		49				50		51	
52		53		54		55				56		57	
58		59		60		61				62		63	
64		65		66		67				68		69	
70		71		72		73				74		75	
76		77		78		79				80		81	
82		83		84		85				86		87	
88		89		90		91				92		93	
94		95		96		97				98		99	
100		101		102		103				104		105	
106		107		108		109				110		111	
112		113		114		115				116		117	
118		119		120		121				122		123	
124		125		126		127				128		129	
130		131		132		133				134		135	
136		137		138		139				140		141	
142		143		144		145				146		147	
148		149		150		151				152		153	
154		155		156		157				158		159	
160		161		162		163				164		165	
166		167		168		169				170		171	
172		173		174		175				176		177	
178		179		180		181				182		183	
184		185		186		187				188		189	
190		191		192		193				194		195	
196		197		198		199				200		201	
202		203		204		205				206		207	
208		209		210		211				212		213	
214		215		216		217				218		219	
220		221		222		223				224		225	
226		227		228		229				230		231	
232		233		234		235				236		237	
238		239		240		241				242		243	
244		245		246		247				248		249	
250		251		252		253				254		255	
256		257		258		259				260		261	
262		263		264		265				266		267	
268		269		270		271				272		273	
274		275		276		277				278		279	
280		281		282		283				284		285	
286		287		288		289				290		291	
292		293		294		295				296		297	
298		299		300		301				302		303	
304		305		306		307				308		309	
310		311		312		313				314		315	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 The cause of the switches being out of Specifications was switch setpoint drift.

2 The instrument (2E51-N018) is an ITT Barton Differential Pressure Switch Procedure

3 HNP-2-5202 was performed to correct the setpoints. HNP-2-3410 was then performed

4 satisfactorily.

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
G (28)										0 0 0 (29)										NA										B (31)										Surveillance Test									
ACTIVITY CONTENT										RELEASED OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																			
Z (33)										(34)										NA										NA																			
PERSONNEL EXPOSURES										NUMBER										TYPE										DESCRIPTION																			
0 0 0 (37)										Z (38)										NA																													
PERSONNEL INJURIES										NUMBER										DESCRIPTION										2230 108																			
0 0 0 (40)																				NA																													
LOSS OF OR DAMAGE TO FACILITY										TYPE										DESCRIPTION										POOR ORIGINAL																			
Z (42)																				NA																													
PUBLICITY										ISSUED										DESCRIPTION										NRC USE ONLY																			
N (44)																				NA																													

NAME OF PREPARER R. T. Nix
Maintenance Superintendent

PHONE: (912) 367-7731

7906150304

100 917-020