

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MDC CN 1 000-0000000-000 411111 5

01 REPORT SOURCE L 050000317 112079 121079 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

At 1315 on November 20, 1979, #12 Containment Cooler was taken out of service to repair the fan motor controller handswitch. The handswitch was repaired and the Containment Cooler returned to service at 1350 on November 20, 1979. This is not a repetitive occurrence. (T.S. 3.6.2.2)

09 SYSTEM CODE SB CAUSE CODE X CAUSE SUBCODE Z COMPONENT CODE CKTB RK COMP. SUBCODE E VALVE SUBCODE Z LER/RO REPORT NUMBER 79 SEQUENTIAL REPORT NO. 066 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0 ACTION TAKEN E FUTURE ACTION Z EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPRD-4 FORM SUB. N PRIME COMP. SUPPLIER A COMPONENT MANUFACTURER G080

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Number 12 Containment Cooler handswitch at Control Room board 1C10 was reported to be sticking in the high speed position. The corrective action was to adjust the spring tension on the switch handle. No further action is required.

15 FACILITY STATUS E % POWER 050 OTHER STATUS N/A METHOD OF DISCOVERY B DISCOVERY DESCRIPTION Operator Observation

16 ACTIVITY CONTENT Z AMOUNT OF ACTIVITY N/A LOCATION OF RELEASE N/A

17 PERSONNEL EXPOSURES NUMBER 0 TYPE Z DESCRIPTION N/A

18 PERSONNEL INJURIES NUMBER 0 DESCRIPTION N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION N/A

20 PUBLICITY ISSUED N DESCRIPTION N/A

1553 357

7912130543

NRC USE ONLY