

APPENDIX A

NOTICE OF VIOLATION

Struthers Wells Corporation
Warren, Pennsylvania 16365
License No. 37-11152-01

Docket No. 30-06249

Based on the results of an NRC inspection conducted on September 17, 1980, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

- A. 10 CFR 34.43(b) requires that a survey be made after each radiographic exposure to determine that the sealed source has been returned to its shielded position. It is required that the entire circumference of the radiographic exposure device be surveyed and if the device has a source guide tube, the survey include the guide tube.

Contrary to this requirement, on September 17, 1980, one of your radiographers failed to perform a survey that was adequate to determine that the sealed source had returned to its shielded container. We note that a survey which was intended to meet this requirement was performed, but was inadequate in that it did not include the entire circumference of the exposure device and the guide tube.

This is an infraction.

- B. 10 CFR 34.43(c) requires that a record of the survey required by 10 CFR 34.43(b) be maintained for two years when the survey is the last survey prior to locking the exposure device and ending direct surveillance of the operation.

Contrary to this requirement, as of September 17, 1980, you have failed to maintain records of the last survey of your radiographic exposure devices prior to locking the device and ending direct surveillance of the operation.

This is a deficiency.